PLANNING/DESIGN

11

1

31

5

12

2

6 24

17

4A)

37

Valued at \$480.3M

June 2024

Ajayan Bridge Replacement Status: Design Completed Estimated Construction Cost: TBD Designer: NC Macario & Associates Estimated start of construction: FY2024

Aplacho Bridge Replacement Status: Design Completed Estimated Construction Cost: TBD Designer: Duenas Camacho & Associates Estimated start of construction: FY2024

Route 10A, Phase 1 Reconstruction and Widening , GIA/Tiyan Intersection Status: Design In Progress Estimated Construction Cost: \$25M Designer: Duenas Camacho & Associates Estimated start of construction: FY2024

Route 14B, Ypao Road, Phase 2 Status: Design Completed Estimated Construction Cost: 12.6M Designer: EM Chen & Associates Estimated start of construction: FY2025

Route 17, Phase 2B

Status: Design Completed Estimated Construction Cost: \$29.3M Designer: Duenas, Camacho & Associates Estimated start of construction: FY2025

Route 20 (Tiyan Parkway), Phase 2 Status: Design Completed Estimated Construction Cost: \$31.4M Designer: TG Engineers Estimated start of construction: FY2027

Route 14 Resurfacing (Route 1 to Archbishop Felixberto Flores Circle): Medians and Sidewalks Status: Design Completed Estimated Construction Cost: \$15M Designer: GHD Estimated start of construction: FY2024

Route 20 Tiyan Parkway Structure Demolition, Phase 2 Status: Planning Estimated Construction Cost: \$750,000 Designer: TBD Estimated start of construction: FY2026

Route 1/8 Memorial Status: Planning Estimated Construction Cost: TBD Designer: TBD Estimated start of construction: TBD

Route 10 Safety Improvements Status: Design Completed Estimated Construction Cost: \$12.5M Designer: WSP USA, Inc. Estimated start of construction: FY2024

Ylig Memorial Status: Design Completed Estimated Construction Cost: \$500,000 Designer: PTG Estimated start of construction: FY2024

Route 1 Pavement Markings Restoration, Juan Jacinto Drive to Gayinero Road (Maintenance) Status: Planning in Progress Estimated Construction Cost: TBD Designer: NA Estimated start of construction: TBD

Route 8 Pavement Markings Restoration, Route 1 to Tri-Intersection (Maintenance) Status: Planning in Progress Estimated Construction Cost: \$354,000 Designer: NA Estimated start of construction: TBD Route 4 Pavement Markings Restoration, Route 1 to Page Bay Bridge (Maintenance) Status: Planning in Progress Estimated Construction Cost: TBD Designer: NA Estimated start of construction: TBD

4

Islandwide Raised Medians Painting, Route 1 (Route 8 to Macy's Entrance), Route 16 (Route 1 to Tri-Intersection), Route 4 (Route 10 to Route 1), Route 8 (Route 1 to Tri-Intersection) Maintenance Status: Planning in Progress Estimated Construction Cost: \$46,000 Designer: NA Estimated start of construction: TBD

Islandwide Accessibility Accomodation and Drainage Improvements Status: Design in Progress Estimated Construction Cost: \$500,000 Designer: WSP USA, Inc. Estimated start of construction: FY2025

Leo Palace Bridge / Pago Bridge Scour Countermeasures Status: Design In Progress Estimated Construction Cost: \$4.6M Designer: GHD Estimated start of construction: FY2026

Fonte Inland, Maina Culvert, & Merizo Inland Culvert Rehabilitation Status: Design in Progress Estimated Construction Cost: \$3.7M Designer: SSFM Estimated start of construction: 2027

Route 2, 4, and Route 4A Planning Study Status: Planning in Progress Estimated Construction Cost: NA Designer: WSP USA, Inc. Estimated Start of construction: NA

Route 1 Reconstruction of Multiple Bridges (Hagatna to Piti) Status: Design in Progress Estimated Construction Cost: \$115.5M Designer: GHD Estimated start of construction: FY2024





- Traffic Signal System Upgrade, Phase 1 Status: Planning Estimated Construction Cost: \$1.5M Designer: TBD Estimated start of construction: FY2025
- Traffic Signal System Upgrade, Phase 2 Status: Planning Estimated Construction Cost: \$2M Designer: TBD Estimated start of construction: FY2025
 - Route 29 Rehabilitation Status: Planning Estimated Construction Cost: \$30M Designer: TBD Estimated start of construction: FY2026

Route 27 Widening Status: Planning Estimated Construction Cost: \$30M Designer: TBD Estimated start of construction: FY2027

Route 6, Rehabilitation from Rt 1 Veteran Cemetery to Rt 1 Adelup Status: Planning Estimated Construction Cost: \$25M Designer: TBD Estimated start of construction: FY2026

Route 26 Widening Status: Planning Estimated Construction Cost: \$17.6M Designer: TBD Estimated start of construction: FY2026


Islandwide Safety Projects Status: Design In Progress Estimated Construction Cost: \$7.5M Designer: TBD Estimated start of construction: FY2024-FY2027

Islandwide Pavement Improvements (Pavement and Pavement Marking) (IDIQ): TO 2 Route 10 Status: Design Completed Estimated Construction Cost: \$1.4M Designer: WSP Estimated start of construction: FY2024

Islandwide Pavement Improvements (Pavement and Pavement Marking) (IDIQ): TO 3 Route 2A, 8, 14A, 30, 32 Status: Design In Progress Estimated Construction Cost: \$1.5M Designer: WSP Estimated start of construction: FY2025

Islandwide Guardrail Repair and Replacement (IDIQ): TO 2 Route 10 Status: Design Completed Estimated Construction Cost: \$0.16M Designer: WSP Estimated start of construction; FY2024

Islandwide Safety Improvements (Striping and Marking) (IDIQ): TO 1 Route 1, Route 11 to Route 6 Status: Design In Progress Estimated Construction Cost: \$1.5M Designer: WSP Estimated start of construction: FY2024





 besigner: DCA Estimated start of construction: TBD
Auto Lot Expansion and Shared Access Road Pavement Status: Design Completed Estimated Construction Cost: \$705,000 Designer: WSP Estimated start of construction: FY2024
Islandwide Traffic Signal Repairs from Typhoon Mawar Status: Planning Estimated Construction Cost: \$1.2M Designer: TBD Estimated start of construction: FY2024

(3A)

25

(28)

27 1

(26

(34) (3)

16

(10)

(32)

10

36 38

9

35

(15)

26

Under Pavement Infrastructure Retrofit

Estimated Construction Cost: \$165.4M

Estimated start of construction: FY2024

Ajayan Bridge Temporary Shoring

Estimated Construction Cost: TBD

Estimated start of construction: TBD

Estimated Construction Cost: \$1M Designer: WSP USA, Inc.

Estimated Construction Cost: TBD

Estimated start of construction: TBD

Estimated Construction Cost: TBD

Estimated start of construction: TBD

Estimated Construction Cost: TBD

Estimated start of construction: FY2026

Route 1 Widening at Rt 26, Rt 27, Signal at

Route 28 from Route 3 to Bumuchachu Road

Route 10A Reconstruction and Widening, GIAA

Islandwide Bridge Safety Improvements

Status: Design In Progress

Status: Design in Progress

Status: Design In Progress

Liguan Ave - Design

Status: Planning

Designer: TBD

Status: Planning

Designer: TBD

to Route 16. Phase 2

Status: Design In Progress

Designer: EMPSCO

Designer: GHD

Islandwide Routed Road Signage Repairs from Typhoon Mawar Damage Status: Planning Estimated Construction Cost: \$1.95M Designer: TBD Estimated start of construction: FY2024

Route 1 Striping Repairs from Route 6 (Adelup to Alupang Towers) from Typhoon Mawar Damage Status: Ranning Estimated Construction Cost: \$350,000 Designer: TBD Estimated start of construction: FY2024

Guatali Bridge Retrofit Status: Planning Estimated Construction Cost: \$15M Designer: TBD Estimated start of construction: FY2025

Route 15 Widening from Route 10 to GPA/GWA Facility Status: Planning Estimated Construction Cost: \$30M Designer: TBD Estimated start of construction: FY2025